

[1] **PRODUCTION QUALITY ASSURANCE NOTIFICATION**



[2] **Equipment or Protective Systems or Components intended for use
in Potentially Explosive Atmospheres
Directive 2014/34/EU**

[3] Notification Number: **DEMKO 09 ATEX Q132948 Rev. 8**

[4] Equipment or Protective System or Components as listed: **Rotary Speed and Position Transducers
Flameproof “d”
Increased Safety “e”
Intrinsic Safety “i”**

[5] Applicant/Manufacturer/Authorized Representative: **Nidec Industrial Solutions
243 Tuxedo Ave, Brooklyn Heights, OH 44131 USA**

[6] Manufacturing locations: **Same as Manufacturer**

[7] UL International Demko A/S, Notified Body number 0539 in accordance with Article 17 and Article 21 of the Council Directive 2014/34/EU of 26 February 2014, notifies that the manufacturer has a production quality system which complies to Annex IV (Module D) of the Directive.
This quality system in compliance to Annex IV (Module D) of the Directive also means the requirements of Annex VII (Module E).

[8] This notification is based on the confidential audit report No.
US/UL/QAR12.0002/10

Results of periodic re-assessments of the quality system are a part of this notification.
The Manufacturer is obliged to inform UL International Demko A/S of any changes in their ISO 9001 registration or other aspects upon which this notification has been given.

[9] This notification is valid until:
2027-01-17

This notification can be withdrawn if the manufacturer no longer satisfies the requirements of Annex IV (Module D) resp. Annex VII (Module E) of the Directive.

[10] According to Article 16[3] of the Directive 2014/34/EU the CE marking shall be followed by the identification number 0539 identifying the notified body involved in the production control phase.

Certification Manager
Thomas Wilson

Date of re-issue: 2023-12-14

Notified Body UL International Demko A/S, Borupvang 5A, 2750 Ballerup, Denmark
Tel. +45 44 85 65 65, info.dk@ul.com, www.ul.com

	Accredited by DANAK under registration number 7011 to certification of products.	Form-ULID-004106 (DCS:00-IC-F0071) – Issue 16.0
	This notification may only be reproduced in its entirety and without any change.	Page 1 of 1